

<p>A8 – Overall view</p>	<p>A8 – Crown condition. Slightly dieback was observed.</p>
 <p>A photograph showing the overall view of tree A8. The tree is supported by a wooden tripod structure and is covered with red safety netting. It is situated in a grassy area with white and red safety barriers in the background. A date stamp '05 10 2024' is visible in the bottom right corner.</p>	 <p>A close-up photograph of the crown of tree A8, showing the foliage and a slight dieback. The tree is supported by a wooden tripod structure. A date stamp '05 10 2024' is visible in the bottom right corner.</p>
<p>A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)</p>	<p>A8 – Trunk and root condition.</p>
 <p>A close-up photograph of the trunk of tree A8, showing a pruning wound. The tree is supported by a wooden tripod structure. A date stamp '05 10 2024' is visible in the bottom right corner.</p>	 <p>A photograph showing the trunk and root condition of tree A8. The tree is supported by a wooden tripod structure and is covered with red safety netting. It is situated in a grassy area with white and red safety barriers in the background. A date stamp '05 10 2024' is visible in the bottom right corner.</p>

<p>A8 – Decaying wound at trunk base</p>	<p>A8 – Decaying wound on trunk</p>
 <p>05 10 2024</p>	 <p>05 10 2024</p>
<p>A12 - Overall View</p>	<p>A12 - Foliage density increased but is still low. Dieback observed.</p>
 <p>05 10 2024</p>	 <p>05 10 2024</p>

<p>A12 – Dieback observed.</p>  <p>05 10 2024</p>	<p>A12 – Trunk and root condition</p>  <p>05 10 2024</p>
<p>A8 – Wound at trunk base</p>  <p>05 10 2024</p>	<p>A8 – Decaying wound on trunk</p>  <p>05 10 2024</p>

Tung Chung New Town Extension – Site Formation and Infrastructure Works at Tung Chung Valley, Phase 1

Manual watering was carried out for A8 during the reporting period. The watering frequency is one to two times per week.



Manual watering was carried out for A12 during the reporting period. The watering frequency is one to two times per week.






CCTV and fencing are in order.



Repenish of mulch (compost) on 10 Oct 2024



<p>CCTV Screen captures at day-time</p>  <p>2024年10月22日 星期二 17:51:50</p> <p>Camera 01</p>	<p>CCTV Screen captures at day-time</p>  <p>2024年10月22日 星期二 17:49:09</p>
<p>CCTV Screen captures at night-time</p>  <p>2024年10月25日 星期五 19:55:50</p> <p>Camera 01</p>	<p>CCTV Screen captures at night-time</p>  <p>2024年10月25日 星期五 19:59:05</p>

Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	A	P	Transplant	There was dieback. Insect feeding signs were previously observed (current infestation rate is low).	Originally located at Site 1. Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened in May 2023 but recovered in Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken and foliage density decreased due to typhoon in Oct 2023.
A12 (T3537)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	P	P	A	Transplant	There was dieback. The foliage density is low. Insect feeding signs were previously observed (current infestation rate is low).	Originally located at Site 5. Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"

Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.

IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species