





<p>A8 – Overall view</p>  <p>08 01 2025</p> <p>This photograph shows a young tree, identified as A8, supported by a tripod structure of wooden poles. The tree is planted in a black mesh tree well. The background features a grey and red plastic safety fence and other trees under a cloudy sky.</p>	<p>A8 – Crown condition.</p>  <p>08 01 2025</p> <p>This photograph provides a close-up view of the upper canopy of tree A8, showing dense green foliage against a bright, cloudy sky.</p>
<p>A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)</p>  <p>08 01 2025</p> <p>This photograph shows a close-up of a pruning wound on the trunk of tree A8. The wound is a vertical cut in the bark, showing the underlying wood. The surrounding leaves are green.</p>	<p>A8 – Trunk and root condition.</p>  <p>08 01 2025</p> <p>This photograph shows the base of tree A8, including the trunk and the tripod support structure. The tree is planted in a black mesh tree well. The background shows the same safety fence and other trees as in the overall view photo.</p>

<p>A8 – Decaying wound at trunk base (size: ~180mm x170mm)</p>	<p>A8 – Decaying wound on trunk</p>
 <p>08 01 2025</p>	 <p>08 01 2025</p>

<p>A12 - Overall View</p>	<p>A12 - Dieback observed. Dead branches were removed on 07/12/2024</p>
 <p>08 01 2025</p>	 <p>08 01 2025</p>
<p>A12 - Foliage density is still low.</p>	<p>A12 – Trunk and root condition</p>
 <p>08 01 2025</p>	 <p>08 01 2025</p>



Tung Chung New Town Extension – Site Formation and Infrastructure Works at Tung Chung Valley, Phase 1

Manual watering was carried out for A8 during the reporting period. The watering frequency is one to two times per week.



Manual watering was carried out for A12 during the reporting period. The watering frequency is one to two times per week.







CCTV and fencing are in order.



Slightly fertilizing was done on 21/01/2025



<p>CCTV Screen captures at day-time</p> <p>2025年02月04日 星期二 16:01:60</p>  <p>Camera 01</p>	<p>CCTV Screen captures at day-time</p> <p>2025年02月04日 星期二 10:58:56</p> 
<p>CCTV Screen captures at night-time</p> <p>2025年02月05日 星期三 18:36:23</p>  <p>Camera 01</p>	<p>CCTV Screen captures at night-time</p> <p>2025年02月05日 星期三 18:34:48</p> 

Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	A	P	Transplant	No specific observation.	Originally located at Site 1. Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened in May 2023 but recovered in Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken and foliage density decreased due to typhoon in Oct 2023.
A12 (T3537)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	P	P	A	Transplant	The foliage density is low.	Originally located at Site 5. Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density. It was slightly lean after a typhoon event dated 13-14 Nov 2024 and reinstated. Removal of dead branches was conducted on 07/12/2024.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022