

A11 – Overall view	A11 – Crown condition.
 11 07 2026	 11 07 2026
A11 – Shoots are epicormic generated from cut trunk which is decaying severely	A11 - Soil condition
 11 07 2026	 11 07 2026

Removal of adjacent undersize trees within the protection zone



Crown cleaning done on 11/07/2026



CCTV Screen



Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A9 (T7628)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	-	-	-	-	-	-	-	-	Removed due to illegal felling on Aug 2023 (reported to police on 21 Aug 2023)
A10 (T7538)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	-	-	-	-	-	-	-	-	Removed due to illegal felling on Aug 2023 (reported to police on 21 Aug 2023)
A11 (T7521)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	190	3.5	1	P	A	P	Retain	Insect infestation is low. Since climbing weeds were observed, crown cleaning was carried out on 11 July 2026. Adjacent undersized trees within the tree protection zone were removed on 11 July 2026.	Root-plate movement (mentioned in previous monitoring report). Topped tree due to illegal felling on Aug 2023 (reported to police on 21 Aug 2023). Large decaying trunk wound. Foliage density reduced after inclement weather events on Aug and Sep 2025. Unknown physical damage is observed resulting in the breaking of some epicormic shoots on Nov 2025 (Cleaned).

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"


Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.

IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species

A8 – Overall view



A8 – Pruning wound previously damaged by typhoon KOINU (Oct 2023)



A8 – Decaying wound on trunk




A8 – Trunk and root condition.



A8 – Decaying wound at trunk base (size: ~180mm x170mm)	A8 –Leaves chlorosis and thin.
 A close-up photograph of the base of a tree trunk. The bark is light-colored and shows a significant, irregularly shaped wound that appears to be decaying. The wound is surrounded by dark, moist soil and some orange plastic mulch. A date stamp '08.07.2026' is visible in the bottom right corner.	 A close-up photograph of tree leaves. The leaves are green but show signs of chlorosis, appearing yellowish-green and somewhat thin. A date stamp '08.07.2026' is visible in the bottom right corner.
A8 – Foliage density reduced after fruiting and repeatedly heavy rains	A8 – Fruits were dropped
 A low-angle photograph looking up at a tree. The foliage is sparse, showing a clear view of the sky and the tree's branches. A date stamp '08.07.2026' is visible in the bottom right corner.	 A photograph of the ground covered with fallen fruits and debris. The ground is dark and appears to be covered with a layer of fallen leaves and small fruits. A date stamp '08.07.2026' is visible in the bottom right corner.

A12 - Overall View	A12 - Dieback observed.
 A photograph showing the overall view of tree A12. The tree is a medium-sized deciduous tree with a dense canopy of green leaves. It is situated behind a black protective netting and a row of white and red plastic safety barriers. The ground is covered with grass and some fallen leaves. The date "08 07 2026" is printed in yellow at the bottom right. 08 07 2026	 A photograph showing a close-up of tree A12, focusing on the upper canopy. The tree shows signs of dieback, with some branches appearing bare and the overall foliage density reduced. The background shows a blue sky with some clouds. The date "08 07 2026" is printed in yellow at the bottom right. 08 07 2026
A12 - Foliage density reduced after repeatedly heavy rains	A12 – Trunk and root condition
 A photograph showing tree A12 with a noticeably reduced foliage density compared to the previous image. The tree is still behind the black netting and safety barriers. The date "08 07 2026" is printed in yellow at the bottom right. 08 07 2026	 A photograph showing a close-up of the trunk and root area of tree A12. The trunk is supported by a wooden frame and wrapped in black protective netting. Orange safety tape is visible around the trunk. The date "08 07 2026" is printed in yellow at the bottom right. 08 07 2026

A12 –Wound at trunk base  08 07 2026	A12 – Decaying wound on trunk  08 07 2026
A12 – Epicormics on trunk. Decaying wound on Trnnk.  08 07 2026	A12 – It is still fruiting  08 07 2026

Fencing is in order during inspection



Grass cutting and weeding was conducted on 14 July 2026.



Manual watering was carried out for A8 during the reporting period. The watering frequency is one to two times per week.




Manual watering was carried out for A12 during the reporting period. The watering frequency is one to two times per week.



Tung Chung New Town Extension – Site Formation and Infrastructure Works at Tung Chung Valley, Phase 1

Systematic insecticide was applied on 8 July 2026



Systematic insecticide was applied on 8 July 2026




Contact insecticide was applied on 21 July 2026



Adjustment of tree supportive system done on 21 July 2026





CCTV Screen captures at day-time 07-23-2026 Thu 15:18:44  CREC TC #214	CCTV Screen captures at day-time 07-23-2026 Thu 15:18:46  CREC TC #215
CCTV Screen captures at night-time 07-13-2026 Mon 01:51:59  CREC TC #214	CCTV Screen captures at night-time 07-13-2026 Mon 01:21:57  CREC TC #215

Tree Schedule for Survey of Plant Species of Conservation Importance

No.	Species		Conservation Status	Measurements			Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation (Retain / Transplant / Remove)	Findings	Remark
	Scientific Name	Chinese name		DBH (mm)	Height (m)	Crown (m)	Form	Health	Structure			
A8 (T8996)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	110	5	4	P	P	P	Transplant	No obvious wound wood production. Severity of the insect feeding was low. Pest control was done on 8 July and 21 July 2026. Adjustment of tree supportive system and crown cleaning were done on 21 July 2026. Fruiting completed.	Trunk wounds were observed before transplant operation. Shallow root. Sudden defoliation happened in May 2023 but recovered in Aug 2023. It was translocated to the temporary holding nursery on 29 Sep 2023. A branch (5cm) was broken due to typhoon in Oct 2023. Decaying wounds and exposed dead woods on trunk. The foliage density is low especially after inclement weather events on Aug/Sep 2025. The tree recovered partially on Spring 2026. However recent heavy raining on June and July resulted in the reduction in foliage density again.
A12 (T3537)	<i>Aquilaria sinensis</i>	土沉香	RPPHK; Cap.586; IUCN:VU	185	8	3	P	P	A	Transplant	No obvious wound wood production. Fruiting. Severity of the insect feeding was low. Pest control was done on 8 July and 21 July 2026. Adjustment of tree supportive system and crown cleaning were done on 21 July 2026. It is still fruiting.	Trunk wounds were observed before transplant operation. Shallow root. Original root ball was full of stones which were removed partially during the translocation. It was translocated to the temporary holding nursery on 29 Sep 2023. It collapsed during typhoon dated Oct 2023 resulted in largely reduction in foliage density. It was slightly lean after a typhoon event dated 13-14 Nov 2024 and reinstated. Decaying wounds and exposed dead woods on trunk. The foliage density is low especially after inclement weather events on Aug/Sep 2025. The tree recovered partially on Spring 2026. However recent heavy raining on June and July resulted in the reduction in foliage density again.

*Note:

DBH refers to Trunk Diameter at Breast Height

The Tree preservation work commenced in Jul 2022

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)"

Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586.

IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species