

1: T8217 2: T8217_Crown



3: T8231 4: U041



5: U041_Crown

6: U041_Dead stump



7: U041_Wood damage at trunk union

8: U041_Wood damaged by termite



9: U042 10: U042_Crown



11: U042_Wound on trunk



13: U043_Crown

14: U043_Wound on trunk#1



15: U043_Wound on trunk#2

16: U043_Wound on trunk#2



17: Spraying of pesticide

18: Readjustment of staking



19: Silt rock and protection zone



20: Temporary protective fencing for U041, U042 $and \ U043$

CEDD Contract No. NL/2020/05 Tung Chung New Town Extension – Site Formation and Infrastructure Works at Ma Wan Chung

Tree Schedule for Survey of Plant Species of Conservation Importance

Tree No.	Species			Measurements			Amenity Value (High(H) /	Tree Condition (Good(G) / Average(A) / Poor(P))			Recommendation		
	Scientific Name	Chinese Name	Conservation Status	Height (m)	DBH (mm)	Crown Spread (m)	Medium (M) / Low(L)	Form	Health	Structure	(Retain / Transplant / Remove)	Findings	Remark
T8217	Canthium dicoccum	魚骨木	IUCN:VU	9	220	6	L	P	Α	P	Retain	No Particular Observation	There is no proper and safe assess towards T8231 & T8217, thus, plastics barriers were installed in lieu of 2m high barrier.
T8231	Canthium dicoccum	魚骨木	IUCN:VU	7	190	6	L	Р	A	P	Retain	No Particular Observation	There is no proper and safe assess towards T8231 & T8217, thus, plastics barriers were installed in lieu of 2m high barrier.
U041	Aquilaria sinensis	土沉香	RPPHK; Cap.586; IUCN:VU	10	318	4	M	A	P	A		No obvious old termite track was found, damage of wood tissue was observed. Application of termiticide is recommended.	Located closed to cut slope and fenced off by 2m high barrier. Application of termiticide and readjustment of staking was conducted on 28 October 2023.
U042	Gmelina chinensis	石梓	RPPHK	6	150	2	М	A	Р	A	Retain	Large wound near trunk base with wound wood development. Application of insecticide is recommended.	Located closed to cut slope and fenced off by 2m high barrier. Application of insecticide and readjustment of staking was conducted on 28 October 2023.
U043	Aquilaria sinensis	土沉香	RPPHK; Cap.586; IUCN:VU	9	310	4	М	Α	Р	A	Retain	Fungal fruiting bodies near trunk base. Application of fungicide is recommended.	Located closed to cut slope and fenced off by 2m high barrier. Application of fungicide and readjustment of staking was conducted on 28 October 2023.

RPPHK - Species included in AFCD publication "Rare and Precious Plants of Hong Kong (2003)" Cap.586 – Native plants listed in Protection of Endangered Species of Animals and Plants Ordinance, Cap. 586. IUCN:VU – "Vulnerable" under IUCN Red List of Threatened Species